

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant							
Inspection Date:	Tuesday, August 11, 2020	Project Contact:	Brian Clauto							
Spread G: Giles	AR-GI 245.01 , 249, 249.03 MP 209.4- 211 ATWS 1366, 1367, 1369	Weather:	Dry							
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)										

Gile	es	ATWS 1366, 1367, 1369		weather.		Dry				
	ACTIVE STAG	E OF CONSTRUCTION: (Che	eck all that	apply)						
	Tree Felling	☐ Clearing/Grubbing	☐ Gra	ding	☐ Tr	enching		Strir	nging/Welding	
	Lowering/Backfilling	☐ Final Grading	☐ Tem	np. Stabilization	□ P6	erm. Stabilization	Stabilization Dormant			
		rols installed and implemented t control plan and stormwater n			roved eros	sion and	Yes	No	N/A	
	Are all co	ontrol measures properly maint d engineering practices and, w	tained in ef	fective operating			\boxtimes			
	3. Areas of	offsite sediment deposition ob	served?					\boxtimes		
Comments: Inspected the following resources: N/A ECD's inspected were functioning and stabilization was in place in areas inspected. Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: N/A Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.										
	Inspector Sig	gnature:	tre Hu							


Date: Tuesday, August 11, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 11, 2020



<u>Figure 2</u>: Near MP 209.4 ECD's are in place and functioning.



Figure 3: Near MP 210 and ATWS 1366



Figure 4: Near MP 210 area is dormant and stabilized

